



# MATERIAL SAFETY DATA SHEET

P.O. BOX 1603  
EUNICE, LA 70535  
866-457-0064 or 337-457-0064

## YELLOW STARCH

### SECTION I - IDENTIFICATION

Manufacturer's Name: Delta Drilling Products & Services, LLC  
Physical Address: 154 Eastpark Drive  
Eunice, LA 70535  
Emergency Number: 866-457-0064 or 337-457-0064  
Chemical Name: Milled Corn Product  
Trade Name: Lincoln Drilling Starch

### SECTION II - HAZARDOUS INGREDIENTS - NOT APPLICABLE

Principal Hazardous Ingredients: None

### SECTION III - PHYSICAL DATA - APPLICABLE AS NOTED

Boiling Point (°F):	N/A	Specific Gravity:	1.10 to 1.25
Vapor Pressure:	N/A	Percent, Volatile by Volume:	N/A
Vapor Density:	N/A	Evaporation Rate:	N/A
Solubility in Water:	20-30%		
Appearance and Odor:	Yellow Flour - Slight Corn Aroma		

### SECTION IV - FIRE AND EXPLOSION HAZARD DATA

Flash Point: N/A  
Extinguishing Media: Water or any commercial fire extinguisher  
Special Fire Fighting Procedures: Avoid creating air suspended flour or dust particles around ignition source.  
Unusual Fire and Explosion Hazards: During mixing operations, avoid creating suspended flour particles and eliminate any source of ignition.

### SECTION V - HEALTH HAZARD DATA - NOT APPLICABLE

Threshold Limit Value: N/A  
Effects of Overexposure: N/A  
Emergency and First Aid Procedures: N/A

### SECTION VI - REACTIVITY DATA - NOT APPLICABLE

Stability: N/A  
Incompatibility: N/A  
Hazardous Decomposition Products: N/A

### SECTION VI - SPILL OR LEAK PROCEDURES

Steps to Be Taken in Case Material is Released or Spilled: Avoid creating air suspended flour or dust particles around ignition source.

Waste Disposal Method: Avoid creating air suspended flour or dust particles during clean up. (Eliminate any source of ignition)

---

<b>SECTION VI - SPECIAL PROTECTION INFORMATION</b>
--

Respiratory Protection:	Respirators advisable if any dust is generated
Ventilation:	Local Exhaust: Exhaust all dust if possible Mechanical: Eliminates any source of ignition.
Protective Gloves:	Recommended.
Eye Protection:	Desirable if any dust is generated.
Other Protective equipment:	N/A

<b>SECTION VII - SPECIAL PRECAUTIONS</b>
--

Precautions To Be Taken In Handling and Storing: Avoid creating air suspended flour or dust particles and any source of  
ignition.

---

<a href="#"><u>HOME</u></a>
-----------------------------

<a href="#"><u>MSDS</u></a>
-----------------------------